## **CWB7 Weight Indicator**







## Functions

- Tare, Units, Net/Gross, Print. Zero, On & Off
- Weighing, Counting & Check weighing (HI-OK-L)
- Bench or Pole Mounting
- 40 mm LCD 6 Digit with white backlight display
- 240 x 105 x 180 mm
- Rechargeable battery for 800 hours of continuous use
- 240 Vac power supply for charging
- Connection to both bench & Floor Platforms

Simple to use the CWB7 Weighing Indicator has a large 40 mm LCD with a white backlit display powered by an internal rechargeable battery for 80 hours continuous use charged via an AC adaptor. Fitted to any size platform scale, column, wall or bench mounted.



## **Phoenix Scales Ltd**

34 Oldbury Road, West Bromwich, B70 9ED

Email:sales@phoenixscales.co.ukTel:0121 520 9048